Annex 6: The template for Incident manager's telephone conference agenda / minutes

Version	Approved by	Date of approval
1.0	RNE General Assembly	May 2021

## 1<sup>st</sup> telco on international disruption Agenda/Minutes

**Date of telco:** 29.10.2022 **Time:** 10:00 – 10:30

## **Participants:**

- Jakub Kuna (ICM for ŽSR)

Roman Stańczak (RFC 11 – PKP SA)

Sándor Balázs (RFC7 - MÁV)

Márk Háry (RFC7 – GySEV)

Daniel Vydra (OSS – SŽDC)

Markéta Šlachtová (Capacity allocation - SŽDC)

Laura Zoppini (RFC 5 - RFI)

Alessandro Turconi (RFC5 - OSS)

Szabolc Tál (RFC11 - MÁV)

## **Enclosures:**



ICM Komárno.pptx

- Two rerouting lines: Štúrovo – Szob // Rusovce – Rajka

Copy:

**Status: Final** 

Date of issue: 25.11.2022 - 00:10

	Topic / Content	Who	Duration
1	Intro	RFC	15
	Participants:	RFC 5	
	- Jakub Kuna (ICM for ŽSR)	RFC 7	
	Roman Stańczak (RFC 11 – PKP SA) Sándor Balázs (RFC7 - MÁV)	RFC 11	
	Márk Háry (RFC – GYSEV)		
	Daniel Vydra (OSS – SŽDC)  Markéta Šlachtová (Capacity allocation - SŽDC)		
	Laura Zoppini (RFC 5 - RFI)		
	Alessandro Turconi (RFC5 - OSS) Szabolc Tál (RFC11 - MÁV)		
	<ul> <li>Information about the closure in Komárno station after accident</li> </ul>		
2	Information about disruption	Leading IM	10

Annex 6: The template for Incident manager's telephone conference agenda / minutes

Version	Approved by	Date of approval
1.0	RNE General Assembly	May 2021

	<ul> <li>Komárno, track 101, nightshift 00:10h, derailing</li> <li>Capacity - total closure</li> <li>The train of RU Railtrans International did not stop at the entrance signal "L", in the standing position in the direction from Komárom (HU), went onto the blind turning track where it broke-through the buffer-stop</li> <li>During the accident operating fluids leaked from the locomotive, ethanol did not leak from the wagons</li> </ul>	ŽSR	
3	Information about actual situation on other networks  - Every freight train was rerouted via Szob or via Rajka until	All	5
	02.12.2022		
4	Re-routing concept (based on developed re-routing overview)	Leading IM	10
	- Štúrovo/Szob or Rusovce/Rajka		
	- Preparation of rough indicative timetable – not needed		
	<ul> <li>Proposal for mitigation measures – usage of reroutings</li> </ul>		
5	International coordination	Leading IM	5
	- Deapartment of dispatchers (HU/SK)		
6	Communication	Leading IM	10
	<ul> <li>ŽSR's representative called for teleconference on 29<sup>th</sup> of November</li> <li>Continuous e-mail exchange</li> <li>News releases</li> </ul>	Communication manager	
7	Specific requirements of telco participants	All	5
	- Inform about situation with email communication after		
	teleconference		
8	Tasks and next steps	RFC	10
	28.11.2022: at 14:28 addition of three tanker wagons for ethanol		
	repump		
	30.11.2022: at 12:00 h tankers repumped at 13:15 h and depart		
	empty tankers from Komárno station to Zlatná na Ostrove		
	Simply tankers from Komarno station to Ziatha na ostrove		
	01.12.2022: leading Loco was re-railed at 18:00h and shunted to Komárno station		

Annex 6: The template for Incident manager's telephone conference agenda / minutes

Version	Approved by	Date of approval
1.0	RNE General Assembly	May 2021

9	Any other business	All	5
	Number of rerouted trains: 54		
	Reroutings Komárno 25_nov - 0;		